BUILDING SAFETY CERTIFICATE

No. 3622

Dated: 26/11/2021

Certified that the St. Paul's Academy, Saheb Kothi, Dariyapur, Bhagalpur, Bihar comprised of Ground Floor, First Floor, Second Floor, Third Floor and Fourth Floor owned by St. Paul Anglo Indian Education Society have complied with the Building Bye Laws in accordance with rule of State/UT, and incorporate the provisions of building safety as specified in National Building Code 2005, 2016 and as amended thereafter and has been verified by the concerned officer on 20 November, 2021 in the presence of Mrs. Kathleen Aleen Quadros, Principal, St. Paul's Academy, Saheb Kothi, Dariyapur, Bhagalpur, Bihar and Mr. Rana Raj Singh, Manager, St. Paul's Academy, Saheb Kothi, Dariyapur, Bhagalpur, Bihar and that the said above building/premises is safe and fit for running School with effect from 26 November, 2021 for a period of ONE YEAR in accordance with rules.

Issued on 26-November-2021 at Bhagalpur Nagar Nigam, Bhagalpur.

* Strike out whichever is not applicable.

Signature with Seal:

Authority: Bhagalpur Nagar N

कार्यपालक अभियंता

Designation: Executive Engineer भागलपुर।

Rhadalnur Nagar Nigam,

Bhagalpur

To.

The Secretary/Principal,

St. Paul's Academy,

Saheb Kothi, Dariyapur,

Bhagalpur, Bihar

ENDORSEMENT

The No Objection Certificate issued by department stand cancelled and annulled due to

ST. PAUĽ'S ACADEMY Dariyapur Sciour Road

BIHAR-812006

Nathnagar, Shagalpur

(Name and designation of the authorized signatory)

Dariyapur, Sajour Road Nathnagar, Bhagalpur

(Reasons to

BIHAR-812006

कार्यपालक अभियंता का कार्यालय,

भवन निर्माण विभाग, भवन प्रमंडल, भागलपुर।

पत्रांक :- 3622 /भागलपुर, दिनांक :- 26·11·2021

प्रेषक.

"**ई० विनय कुमार सिंह"** कार्यपालक अभियंता, भवन प्रमंडल, भागलपुर।

सेवा में.

प्राचार्य, सेंट पॉल एकंडमी, साहेब कोठी, ग्रा०+पो०—दरियापुर, भागलपुर.

विषय :-

सेंट पॉल एकेडमी स्कूल, साहेब कोठी, दरियापुर, भागलपुर का भवन सुरक्षा प्रमाण पत्र निर्गत करने के संबंध में।

प्रसंग :--

आपका पत्र दिनांक 05.11.2021

महाशय,

उपर्युक्त विषयक प्रासंगिक पत्र के कम में सहायक अभियंता, भवन अवर प्रमंडल सं0–01, भागलपुर के पत्रांक 78 दिनांक 18.11.2021 से प्राप्त प्रतिवेदन के आधार पर कहना है कि सेंट पॉल एकेडमी स्कूल, साहेब कोठी, दिर्यापुर, भागलपुर का निरीक्षण कनीय अभियंता/सहायक अभियंता के द्वारा किया गया। निरीक्षणोपरांत सामान्य परिस्थिति में उक्त स्कूल भवन सुदृढ़ पाया गया।

अतः उक्त स्कूल भवन सामान्य परिस्थिति में पठन पाठन कार्य के लिए सुदृढ़ है।

मानकः असियता, य प्रमुख्यः मागङ्गास्य।

到一种

ST, PAUL'S ACADEMY
Dariya our Road
Native angaipur

BIHAK-812006

ST. PAUL'S ACADEMY Dariyapur, Sajour Road Nathnaar, Bhagalpur

BIHAR-812006